| Operator: NORTHERN ILLINOIS GAS CO. | Operator ID#: 13710 | | |
|--|---------------------|--|--|
| Inspection Date(s): 10/23/2012, 10/24/2012, 10/25/2012 Man Days: 3 | | | |
| Inspection Unit: NICOR - Kankakee | · | | |
| Location of Audit: Peotone | | | |
| Exit Meeting Contact: Steve Canestrini | | | |
| Inspection Type: Standard Inspection - Field Audit | | | |
| Pipeline Safety Representative(s): Kevin Ketchum | | | |
| Company Representative to Receive Report: Leticia Quezada | | | |
| Company Representative's Email Address: Iquezad@aglresources.com | | | |

| Headquarters Address Information: | P. O. Box 190 | |
|-----------------------------------|-------------------------|----------------|
| | Rt. 59 & I-88 | |
| | Aurora, IL 60507 | |
| | Emergency Phone#: | |
| | Fax#: | |
| Official or Mayor's Name: | Ralph Cleveland | |
| | Phone#: (000) 000-0000 | |
| | Email: | |
| Inspection Contact(s) | Title | Phone No. |
| Steve Canestrini | Programs Administration | (815) 754-3136 |

| | Status | | | | |
|---|--|--------------|--|--|--|
| Category Comment: | | | | | |
| Residential meter sets v | vere inspected during this audit. | | | | |
| 100-300 blocks of W Cr 200 block of N 2nd St | awford | | | | |
| 200 block of N West St 300-400 blocks of E No. | 200 block of N West St | | | | |
| 100 block of N Fourth S | t e | | | | |
| 100 block of East Railro | ad St | | | | |
| 192.353(a) | Is the customer meter and regulator installed in a readily accessible location and protected from corrosion and other damage, including if installed outside a building, vehicular damage that may be anticipated? | Satisfactory | | | |

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

| 192.355(b)(1) | Is the customer regulator vent rain and insect resistant? | Satisfactory |
|---------------|--|--------------|
| 192.355(b)(2) | Is the customer regulator vent located where gas from the vent escapes freely into the atmosphere and away from building openings? | Satisfactory |
| 192.355(b)(3) | Is the vent protected from damage caused by submergence in areas of flooding? | Satisfactory |
| 192.357(a) | Is the customer meter and regulator installed to minimize anticipated stresses upon connecting piping? | Satisfactory |
| 192.357(d) | Is a customer regulator that might release gas vented to the outside atmosphere? | Satisfactory |
| 192.359(a) | Is the meter operating pressure within the allowable limits of the meter case rating? | Satisfactory |
| 192.365(a) | Is the service line valve upstream of the regulator or meter? | Satisfactory |
| 192.365(c) | Is the service line valve located in a curb box or stand pipe that allows for ready operation? | Satisfactory |
| 192.727(d) | When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage? | Satisfactory |
| | Status | |

Category Comment:

| Address | Readings |
|------------------------------------|----------|
| 316 North 2 nd . St. | -1.17 |
| 517 North West St. | -1.42 |
| North West Corner Rail Rd. | -1.31 |
| 416 Crawford St. | -1.10 |
| 346 Harlem St. | -1.04 |
| 337 West Crawford St. | -1.27 |
| 324 North St. | -1.27 |
| 108 West Summer St. | -1.28 |
| 501 North Conrad St. | -1.25 |
| 115 North Conrad St. | -1.28 |
| 608 Royal St. | -1.12 |
| Rathje Rd. | -1.40 |
| Corner of Corning St. and Mill St. | -1.32 |
| 429 Blain St. | -1.21 |
| 409 West Garfield | -1.20 |
| 301 Vangogh St. | -1.49 |

| 192.614(c)(5) | | Were temporary markings made in accordance with the operator's Operation and Maintenance Manual? | | |
|--|------------------------------|--|--|--------------|
| A Damage prevention ins | spection was not con | ducted during | g this audit. | |
| General Comment: | | | | |
| ADM. CODE 265.40(a) | Did the opera | Did the operator complete the locating activities in the specified timeframe? | | |
| A Damage prevention ins | spection was not con | ducted during | g this audit. | |
| General Comment: | | | | |
| 192.614 | Does the ope | rator have | a valid notification of planned excavation activities? | Not Checked |
| | | DAMAG | GE PREVENTION | Status |
| 192.479(c) | Is the pipeline | e free of co | prrosion or pitting? | Satisfactory |
| 192.479(a) | Is the above | Is the above ground piping coated or painted as required? | | |
| A casings inspection was | s not conducted durin | ng this audit. | | |
| General Comment: | TVVCIO Oddings | , indianatio | no todica for cicotrical iodianott: | Not Checked |
| 192.467(a) | flange? | Is electrical isolation provided by use of insulated meter spud, valve, union, or flange? Were casings installations tested for electrical isolation? | | |
| A bonds inspection was r 192.467(a) | | | ovided by use of insulated meter sould valve union or | Satisfactory |
| General Comment: | | | | |
| 192.465(c) | Were critical/ | non critica | I bonds tested? | Not Checked |
| 192.465(a) | | | rvices tested? | Satisfactory |
| A rectifier inspection was | | | | |
| General Comment: | | | | |
| 192.465(b) | Were rectifier | installatio | ns inspected? | Not Checked |
| 192.465(a) | Were pipe to | soil readin | gs taken? | Satisfactory |
| 192.463(a) | Is the applica being followe | | lic protection criteria contained in Appendix D of this part | Satisfactory |
| 530 Joliet Rd. | | -1.46 | | |
| 405 North Mill St. | | -1.44 | | |
| 629 Oak St. | | -1.41 | | |
| 312 Brinker Dr. | | -1.50 | | |

| General Comment: | | | | |
|--|--|-------------|--|--|
| A Damage prevention ir | nspection was not conducted during this audit. | | | |
| 192.707(a)(1) | Are line markers placed and maintained as close as practical over each buried main and transmission line located at each crossing of a public road and railroad? | Not Checked | | |
| General Comment: | | | | |
| A Damage prevention ir | nspection was not conducted during this audit. | | | |
| 192.707(a)(2) | Are line markers placed and maintained as close as practical over each buried main and transmission line located wherever necessary to identify the location of the transmission line or main to reduce the possibility of damage or interference? | | | |
| General Comment: | | | | |
| A line marker inspectior | was not conducted during this audit. | | | |
| 192.707(c) | Not Checked | | | |
| General Comment: | | | | |
| A line marker inspectior | was not conducted during this audit. | | | |
| 92.707(d)(1) Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line marker: The word "Warning," "Caution," or "Danger" followed by the words "Gas (or name of gas transported) Pipeline" all of which, except for markers in heavily developed urban areas, must be in letters at least 1 inch (25 millimeters) high with 1/4 inch (6.4 millimeters) stroke? | | Not Checked | | |
| General Comment: | | | | |
| A line marker inspectior | was not conducted during this audit. | | | |
| 92.707(d)(2) Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line marker: The name and phone number (including area code) of the operator where the operator can be reached at all times? | | Not Checked | | |
| General Comment: | | | | |
| A line marker inspectior | was not conducted during this audit. | | | |
| PRESS | URE LIMITING AND REGULATING DEVICES (MECHANICAL) | Status | | |
| Category Comment: | | | | |
| The following stations w | vere inspected during this audit. No deficiencies were noted. | | | |
| Station Number | | | | |

| 4004407 | \neg | | |
|------------------|--------------|--|--------------|
| 4301407 | | | |
| 4371115 | | | |
| 4301400 | | | |
| 4301422 | | | |
| 192.739(a)(4) | Satisfactory | | |
| 192.317(b) | | s each above ground transmission line or main protected from accidental damage y vehicular traffic or other similar causes? | Satisfactory |
| | | Vere telemetering and/or recording gauges inspected for abnormally high or low ressure indications? | Satisfactory |
| 192.743(a) | ls | s overpressure protection provided on the pipeline down stream of the take point? | Satisfactory |
| | | oid the pressure relief or pressure limiting devices inspected to determine if the upport was made of noncombustible material? | Satisfactory |
| dis wa | | bid the pressure relief or pressure limiting devices inspected to determine if the ischarge stacks, vents, or outlet ports were designed to prevent accumulation of vater, ice, or snow, and located where gas can be discharged into the atmosphere vithout undue hazard? | Satisfactory |
| p | | Vas each valve, designed to isolate the system under protection from its source of ressure, secured to prevent unauthorized operation of any stop valve that will nake the pressure relief valve or pressure limiting device inoperative? | Satisfactory |
| | | VALVE MAINTENANCE | Status |
| Category Comment | <u>t:</u> | | |
| Valve Number | Function | on | |
| 4314004 | Fire | | |
| 4314001 | Inlet | | |
| 4314002 | Bypas | S | |
| 4314003 | Outlet | | |
| 4314220 | Gate | | |
| 4314221 | Fire | | |
| 4314222 | Inlet | | |
| 4314223 | Bypas | S | |

| 4314224 | Outlet | t | |
|--------------------|-----------------|--|--------------|
| 4317107 | Line | | |
| 4368510 Bypass | | SS SS | |
| 4368521 | Line | | |
| 4371104 | Line | | |
| 4368511 | Inlet | | |
| 4371105 | Fire | | |
| 4371106 | Fire | | |
| 192.747(a) | V | Were the valves inspected accessible? | Satisfactory |
| | | ODORIZATION OF GAS | Status |
| Category Comm | ent: | | • |
| An Odorization in: | spection wa | s not conducted during this audit. | |
| 192.625(a) | \ | Was the odor intensity level readily detectable at or below 1/5th LEL? | Not Checked |
| 192.625(e) | \ | Was the Odorization equipment and tank levels inspected? | Not Checked |
| 192.625(f) Was the | | Was the operator's equipment calibrated as required? | Not Checked |
| TRANSMISSION | | Status | |
| Category Comm | ent: | | • |
| A Transmission in | spection wa | as not conducted during this audit. | |
| 192.179(b)(1) | , | Are transmission valves protected from tampering or damage? | Not Checked |
| 192.745(a) Wer | | Were the valves inspected accessible? | Not Checked |
| 192.719(a) | I | s pre-tested transmission pipe inventory maintained for use in an emergency? | Not Checked |
| | | MARKING OF MATERIAL | Status |
| Category Comm | ent: | | • |
| A Marking of Mate | erial inspecti | ion was not conducted during this audit. | |
| 192.63(a) | I | Does the operator's components and pipe contain the required markings? | Not Checked |
| | | OPERATOR QUALIFICATION | Status |
| Category Comm | ent: | | |
| An Operator Qual | lification insp | pection was not conducted during this audit. | |
| Mas a DUMS/ | \ Form 15 | Operator Qualification Field Inspection Protocol Form completed? | No |